

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PA 41-9 Pad

Location ID: 334964



Photo # 4171 From entrance to location



Photo # 4172 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PA 41-9 Pad

Location ID: 334964



Photo # 4173 Location



Photo # 4174 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PA 41-9 Pad

Location ID: 334964



Oct 24, 2023 at 2:08:45 PM
CO



Oct 24, 2023 at 2:06:26 PM
CO

Photo # 4175 Location

Photo # 4176 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PA 41-9 Pad

Location ID: 334964



Photo # 4177 Open ended pipe/wildlife hazard



Photo # 4178 Open ended pipe/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA PA 41-9 Pad

Location ID: 334964



Photo # 4179 Unused equipment