

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MITCHELL GV 75-3 Pad

Location ID: 311559



Photo # 4086 From entrance to location



Photo # 4087 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MITCHELL GV 75-3 Pad

Location ID: 311559



Photo # 4088 Location



Photo # 4089 Location





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MITCHELL GV 75-3 Pad

Location ID: 311559




Photo # 4090 Location



Photo # 4091 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MITCHELL GV 75-3 Pad

Location ID: 311559



Photo # 4092 Location



Photo # 4093 Tank label lacks required information



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MITCHELL GV 75-3 Pad

Location ID: 311559



**Photo # 4094 Open ended pipe on production tank/wildlife hazard**



**Photo # 4095 Open ended pipe on production tank/wildlife hazard**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MITCHELL GV 75-3 Pad

Location ID: 311559



Photo # 4096 Open ended load line