

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 3NESE

Location # 311559

Facility # 456925



Photo # 4100 Domestic tap



Photo # 4101 Domestic tap – 1 inch line coming off casing valve

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 3NESE

Location # 311559

Facility # 456925




Photo # 4102 Domestic tap



Photo # 4103 Domestic tap

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 3NESE

Location # 311559

Facility # 456925



Photo # 4104 Domestic tap



Photo # 4105 Domestic tap