

Inspection Photos

Operator: SCOUT ENERGY MANAGEMENT LLC - 10779


Location Name: SHARPLES-MCLAUGHLIN #8-33

Location ID: 311807 API #: 05-103-06289

Inspection Date: 10/26/2023 Inspection Doc#: 693806501



Injection well during MIT



Form 21 field copy