

Inspection Photos

Loc: 309096

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 10/26/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast at the location. There is a pile material that remains at the location with a compacted berm.



Inspection Photos



Photo 2. The well sign is posted at meter shed.



Inspection Photos



Photo 3. Facing toward the pit on location which appears to be in process for closure.

