

Inspection Photos

Loc: 333446

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 10/27/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest toward the access road. There is erosion along the road that needs to be repaired..



Inspection Photos



Photo 2. Facing northeast at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:333446 | Date: 10/27/2023