

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203

Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403575609

Receive Date:

Report taken by:

Site Investigation and Remediation Workplan (Initial Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>PDC ENERGY INC</u>	Operator No: <u>69175</u>	Phone Numbers
Address: <u>1099 18TH STREET SUITE 1500</u>		Phone: <u>(970) 313-5582</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Jason Davidson</u>	Email: <u>FRspillremediationcontractor@pdce.com</u>	Mobile: <u>()</u>

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: _____ Initial Form 27 Document #: 403575609

PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☒ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☒ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☐ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☐ Rule 915.b: Request to leave elevated inorganics in situ.
- ☐ Other: _____

SITE INFORMATION

No Multiple Facilities

Facility Type: <u>LOCATION</u>	Facility ID: <u>433548</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>Phelps 12-32NHZ</u>		Latitude: <u>40.010042</u>	Longitude: <u>-104.792577</u>
		** correct Lat/Long if needed: Latitude: <u>40.011100</u>	Longitude: <u>-104.792570</u>
QtrQtr: <u>SENE</u>	Sec: <u>32</u>	Twp: <u>1N</u>	Range: <u>66W</u>
		Meridian: <u>6</u>	Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SM

Most Sensitive Adjacent Land Use Agricultural

Is domestic water well within 1/4 mile? Yes

Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

Unnamed Drainage and associated Wetland: 100' S
Irrigation Ditch: 630' SW
Unnamed Ponds: 600' S, 580' SE, and 1,200' N
Livestock: 660' N and 1,190' NW
Domestic Water Wells: 845' NW, 1,110' SE, 1,120' SE, 1,180' NE, 1,210' SE, and 1,300' SE
Residential Properties: 1,040' N, 1,130' S, and 1,160' SE

No other potential receptors are located within 1/4 mile of the Site.
Above distances are approximations.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | |
| <input checked="" type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input checked="" type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	GROUNDWATER	Unknown	Not yet determined
Yes	SOILS	6' x 8' x 3' deep	Confirmation Soil Sampling

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

On 8/19/23, a broken site glass on the Phelps 11-32 CHZ separator resulted in the release of less than 1 barrel of produced fluids. Impacted surface soil was excavated using a hydrovac.

During additional soil removal activities on 8/21/23, groundwater was encountered at a depth of approximately 3 feet below ground surface (bgs). Free phase condensate was observed on the surface of the groundwater.

Approximately 3 cubic yards of impacted soil and groundwater were removed from the impacted area via hydrovac and transported to Republic Services Tower Road Landfill in Commerce City, CO for disposal under PDC manifest in accordance with Rules 905 and 906. Copies of the waste manifests are available upon request.

Soil samples were collected on 8/23/23 and analyzed for the full ECMC Table 915-1 suite of analytes by ECMC approved methods. A grab groundwater sample was also collected from the base of the excavation and analyzed for ECMC Table 915-1 Organic Compounds in Groundwater by ECMC approved methods. The laboratory data are summarized in Tables 1 to 6 and illustrated on Figure 3.

Based on the laboratory data, petroleum constituents in the unsaturated soil have been adequately remediated. However, arsenic, barium, electrical conductivity (EC) and/or sodium adsorption ratio (SAR) concentrations were above the ECMC Table 915-1 standards in the soil samples. Further, the benzene concentration in the groundwater sample exceeded the ECMC Table 915-1 standard.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

- ☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

As shown on Figure 4, five groundwater monitoring wells are proposed. One soil sample will be collected from each soil boring and analyzed for the full ECMC Table 915-1 suite of analytes. In addition, five background soil borings will be advanced to collect background soil samples for analysis of arsenic, barium, EC, and SAR by ECMC approved methods. The proposed locations of the soil borings for background samples are also shown on Figure 4.

Proposed Groundwater Sampling

- ☒ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Groundwater impacts remain at the Site and the magnitude and extent of these impacts require additional delineation. As shown on Figure 4, five monitoring wells are proposed. One groundwater sample will be collected from each monitoring well and analyzed for ECMC Table 915-1 Organic Compounds and Inorganic Parameters in Groundwater by ECMC approved methods. Groundwater sampling and analyses will be completed on a quarterly basis until four consecutive ECMC-compliant quarters are achieved. At that time, a request for a no further action (NFA) determination will be submitted.

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Since groundwater was impacted immediately following the release, five groundwater monitoring wells are proposed to delineate the extent of groundwater impacts. The locations of these proposed monitoring wells are shown on Figure 4.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 6

Number of soil samples exceeding 915-1 6

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 48

Groundwater

Number of groundwater samples collected 1

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet) 3

Number of groundwater monitoring wells installed 0

Number of groundwater samples exceeding 915-1 1

Surface Water

0 Number of surface water samples collected

 Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

NA / ND

-- Highest concentration of TPH (mg/kg) 650

-- Highest concentration of SAR 12.6

BTEX > 915-1 Yes

Vertical Extent > 915-1 (in feet) 3

-- Highest concentration of Benzene (µg/l) 14

ND Highest concentration of Toluene (µg/l)

ND Highest concentration of Ethylbenzene (µg/l)

-- Highest concentration of Xylene (µg/l) 22

NA Highest concentration of Methane (mg/l)

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☒ Is further site investigation required?

Refer to the Proposed Soil Sampling, Proposed Groundwater Sampling, and Additional Investigative Actions sections of this Form 27.

REMEDIAL ACTION PLAN

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

On 8/19/23, during initial excavation activities, impacted surface soils were removed using a hydrovac.

During additional soil removal activities on 8/21/23, approximately 3 cubic yards of impacted soil and groundwater were removed from the impacted area via hydrovac and transported to Republic Services Tower Road Landfill in Commerce City, CO for disposal under PDC manifest in accordance with Rules 905 and 906. Copies of the waste manifests are available upon request.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Dissolved phase groundwater impacts remain on site following the removal of impacted soils. No further excavation is required. Soil borings completed as monitoring wells will be installed within and adjacent to the excavation to define the magnitude and extent of residual groundwater impacts. After four consecutive quarters of groundwater samples are in compliance with the ECMC Table 915-1 standards, a NFA designation will be requested.

Refer to the Source Removal Summary above.

Soil Remediation Summary

☐ In Situ

☒ Ex Situ

_____ Bioremediation (or enhanced bioremediation)

Yes _____ Excavate and offsite disposal

_____ Chemical oxidation

_____ If Yes: Estimated Volume (Cubic Yards) _____ 3

_____ Air sparge / Soil vapor extraction

_____ Name of Licensed Disposal Facility or COGCC Facility ID # _____

_____ Natural Attenuation

_____ Excavate and onsite remediation

_____ Other _____

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

Yes _____ Other _____ Removed via hydrovac and transported to Republic Services Tower Road Landfill in Commerce City, CO.

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was encountered at a depth of approximately 3 feet bgs at the Site. Free phase condensate was observed on the surface of the groundwater. Refer to the Proposed Groundwater Sampling section of this Form 27.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

☒ Quarterly☐ Semi-Annually☐ Annually☐ Other

☐ Request Alternative Reporting Schedule:

☐ Semi-Annually☐ Annually☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type:

☒ Groundwater Monitoring☐ Land Treatment Progress Report☐ O&M Report☐ Other

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Operator does not have site-specific financial assurance for this project; however, Operator has inactive well, blanket, and surface bonding including Surety IDs 106077122, 106473808, and 106473820, as well as commercial general liability and/or umbrella/excess insurance meeting the requirements of Rule 705.b. Operator does not anticipate making an insurance claim for this project.

- Source mass removal is complete
- Proposed background soil investigation to evaluate residual arsenic, barium, EC, and SAR levels and groundwater monitoring well installation activities will commence within 90 days following the submittal of this Initial Form 27.

Costs included herein are estimates only and may change over time based on numerous factors. Accordingly, Operator makes no guarantees as to the accuracy of such cost estimates, thus providing an estimate for the next year below.

Operator anticipates the remaining cost for this project to be: \$ 45000

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

No beneficial use

Volume of E&P Waste (solid) in cubic yards 3

E&P waste (solid) description Hydrocarbon impacted soil

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility: Republic Services Tower Road
Landfill in Commerce City, CO

Volume of E&P Waste (liquid) in barrels 0

E&P waste (liquid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The Phelps12-32NHZ facility is an active facility and there are no current plans for decommissioning or reclamation activities.

Is the described reclamation complete? _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim ☐ Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. _____

Proposed date of completion of Reclamation. _____

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 08/24/2023

Actual Spill or Release date, or date of discovery. 08/21/2023

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 08/19/2023

Proposed site investigation commencement. 08/21/2023

Proposed completion of site investigation. 01/31/2024

REMEDIAL ACTION DATES

Proposed start date of Remediation. 08/19/2023

Proposed date of completion of Remediation. 08/23/2023

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☐ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Jason Davidson

Title: Senior Env. Specialist

Submit Date: _____

Email: FRspillremediationcontractor@pdce.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

Remediation Project Number: _____

COA Type**Description**

0 COA	

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

403575613	SITE INVESTIGATION REPORT
-----------	---------------------------

Total Attach: 1 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)