

# Inspection Photos

Loc: 309185

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 10/27/2023

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northeast toward the recontoured location. The vegetation to at least 80% cover.



## Inspection Photos



**Photo 2.** Facing east at the location. Perennial vegetation has fully re-established.



## Inspection Photos



**Photo 3.** Facing northeast at the location. Perennial vegetation has fully re-established.



## Inspection Photos



**Photo 4.** Center of the location facing northeast. Perennial vegetation has fully re-established.

