

Inspected Facilities

Facility ID: 261022 Type: WELL API Number: 123-20557 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI LOTO Form 06A doc #403108165

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 07/13/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
Follow up inspection to Doc# 702402312 in response to FIRR #403522780. Based on photos submitted be operator corrective actions are complete. (Photos attached to FIRR)	revasr	10/30/2023