



**Inspected Facilities**

Facility ID: 286081 Type: WELL API Number: 123-24109 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI, Form 06A doc # 403213985

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 08/28/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Follow up inspection to Doc# 702402299 in response to FIRR #403529380. Based on photos submitted be operator corrective actions are complete. (Photos attached to FIRR)	revasr	10/30/2023