

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: OLIVE-62N66W 26NESW

Loc ID: 336338

Inspection: 702402422



Exhibit A



Exhibit B



Exhibit C

CA: Trash and dead vegetation around the wellsite. Comply with Rule 606.

CA Resolution: Operator has addressed and appropriately cleared the identified trash and dead vegetation on location to comply with Rule 606.