

# Final Reclamation Inspection

October 12th, 2023

Operator: Simcoe LLC - 10749

Location ID: 325537

Inspection Document #: 714000050

La Plata County, CO

Township: SENW 31 35N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: State Chastain 01-31 1  
Location ID: 325537



**Photo 1.** View of the well disturbance taken from the entrance facing center.



API #: 067-06571



Inspection Photos  
Location Name: State Chastain 01-31 1  
Location ID: 325537



**Photo 2.** View of the southern interim reclamation area facing south.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-06571



Inspection Photos  
Location Name: State Chastain 01-31 1  
Location ID: 325537



10/12/23  
+37.261654,-107.790027  
213° SW

**Photo 3.** View of the western interim reclamation area facing southwest.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-06571



Inspection Photos  
Location Name: State Chastain 01-31 1  
Location ID: 325537



**Photo 4.** View of farm equipment stored in the northern interim reclamation area.





Inspection Photos  
Location Name: State Chastain 01-31 1  
Location ID: 325537



**Photo 5.** View of unused fencing equipment stored on location.



Inspection Photos  
Location Name: State Chastain 01-31 1  
Location ID: 325537



**Photo 5.** View of undesirable vegetation (kochia) in various locations throughout the disturbance that is now considered debris.