

Final Reclamation Inspection

October 12th, 2023

Operator: Hilcorp Energy LLC - 10133

Location ID: 326291

Inspection Document #: 714000052

La Plata County, CO

Township: NESE 6 34N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SE Durango Wride 6-1
Location ID: 326291



10/12/23
+37.242231,-107.781241
115° SE

Photo 1. View of the well disturbance from the entrance facing Southeast.



10/12/23
+37.242231,-107.781241
38° NE

Inspection Photos
Location Name: SE Durango Wride 6-1
Location ID: 326291



10/12/23
+37.242146,-107.781303
146° SE

Photo 2. View of the southern interim reclamation area facing southeast.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07787

Inspection Photos
Location Name: SE Durango Wride 6-1
Location ID: 326291



Photo 3. View of the eastern interim reclamation area facing northeast.

Inspection Photos
Location Name: SE Durango Wride 6-1
Location ID: 326291



Photo 4. View of musk thistle flowering on location, approximately 10 individuals observed.



Inspection Photos
Location Name: SE Durango Wride 6-1
Location ID: 326291



Photo 5. Reference area is an agricultural grass field.

