

# Final Reclamation Inspection

October 12th, 2023

Operator: Enduring Resources LLC - 10633

Location ID: 326115

Inspection Document #: 714000053

La Plata County, CO

Township: SWSE 35 35N 9W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Day V Ranch 35-2  
Location ID: 326115



**Photo 1.** View of the project area taken from the entrance facing center.



Inspection Photos  
Location Name: Day V Ranch 35-2  
Location ID: 326115



**Photo 2.** Musk thistle observed flowering on location.  
Approximately 100 individuals observed.

Inspection Photos  
Location Name: Day V Ranch 35-2  
Location ID: 326115



**Photo 3.** Reference area comprised of gambel oak, crested wheatgrass and smooth brome.

Inspection Photos  
Location Name: Day V Ranch 35-2  
Location ID: 326115



Photo 4. View of closed gates before leaving (left) and after leaving (right).