

Final Reclamation Inspection

October 26th, 2023

Operator: Enduring Resources LLC - 10663

Location ID: 325538

Inspection Document #: 714000062

La Plata County, CO

Township: SWNE 7 34N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Freienmuth 1-7
Location ID: 325538



Photo 1. View of eastern interim reclamation facing north.

Inspection Photos
Location Name: Freienmuth 1-7
Location ID: 325538



10/26/23
+37.233121,-107.783402
165° S

Photo 2. View of western interim reclamation area facing west.

Inspection Photos
Location Name: Freienmuth 1-7
Location ID: 325538



Photo 3. Debris observed on the western edge of the disturbance.

Inspection Photos
Location Name: Freienmuth 1-7
Location ID: 325538



Photo 4. A Colorado list C noxious plant species (Mullein) observed in several locations throughout the disturbance.

Inspection Photos
Location Name: Freienmuth 1-7
Location ID: 325538



Photo 5. Reference area comprised of smooth brome and yellow sweet clover.