

Final Reclamation Inspection

October 26th, 2023

Operator: Enduring Resources LLC - 10663

Location ID: 333643

Inspection Document #: 714000064

La Plata County, CO

Township: NWSE 7 34N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO


**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Clark 7-2
Location ID: 333643



Photo 1. View of the well disturbance taken from the entrance facing center.



API #: 067-09036

Inspection Photos
Location Name: Clark 7-2
Location ID: 333643



Photo 2. View of the southern reclamation area facing west.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09036

Inspection Photos
Location Name: Clark 7-2
Location ID: 333643



Photo 3. View of the western interim reclamation area facing north.



Inspection Photos
Location Name: Clark 7-2
Location ID: 333643



Photo 4. Reference area comprised of smooth brome.