

# Final Reclamation Inspection

October 26th, 2023

Operator: Simcoe LLC - 10749

Location ID: 326263

Inspection Document #: 714000066

La Plata County, CO

Township: NENW 15 34N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Annala Federal A 1  
Location ID: 326263



**Photo 1.** View of the well disturbance taken from the entrance facing center.



API #: 067-07741

Inspection Photos  
Location Name: Annala Federal A 1  
Location ID: 326263



**Photo 2.** View of the eastern interim reclamation area facing northwest.

Inspection Photos  
Location Name: Annala Federal A 1  
Location ID: 326263



**Photo 3.** View of the southern interim reclamation area facing southeast.

Inspection Photos  
Location Name: Annala Federal A 1  
Location ID: 326263



**Photo 4.** View of stormwater BMPs in the southern interim reclamation area. Erosional scouring and sediment transport remains.

Inspection Photos  
Location Name: Annala Federal A 1  
Location ID: 326263



**Photo 4.** Reference area comprised of sagebrush, juniper, poa secunda and western wheat grass.