

Final Reclamation Inspection

October 26th, 2023

Operator: Simcoe LLC - 10749

Location ID: 326547

Inspection Document #: 714000069

La Plata County, CO

Township: SWNE 17 34N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: James Cole A 2
Location ID: 326547

10/26/23
+37.218369,-107.765244
156° SE



10/26/23
+37.218272,-107.765206
129° SE

Photo 1. View of the well disturbance taken from the entrance facing center.

Inspection Photos
Location Name: James Cole A 2
Location ID: 326547



Photo 2. View of the eastern interim reclamation area facing southeast.

Inspection Photos
Location Name: James Cole A 2
Location ID: 326547



Photo 3. View of gravel stored on the well disturbance.
this is considered debris and needs to be removed.

Inspection Photos
Location Name: James Cole A 2
Location ID: 326547



Photo 4. Reference area comprised of hay grass field.