

Final Reclamation Inspection

October 26th, 2023

Operator: Simcoe LLC - 10749

Location ID: 326249

Inspection Document #: 714000070

La Plata County, CO

Township: NENW 17 34N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: James Cole A 1
Location ID: 326249



10/26/23
+37.219336,-107.773370
15° N



Photo 1. View of the well disturbance taken from the entrance facing center.

Inspection Photos
Location Name: James Cole A 1
Location ID: 326249



Photo 2. View of the western interim reclamation area facing southwest.

Inspection Photos
Location Name: James Cole A 1
Location ID: 326249



Photo 3. View of trash/debris observed on location.

Inspection Photos
Location Name: James Cole A 1
Location ID: 326249



Photo 4. Reference area. Disturbance is surrounded by a prairie dog colony with minimal vegetation.