

Final Reclamation Inspection

October 26th, 2023

Operator: Simcoe LLC - 10749

Location ID: 334302

Inspection Document #: 714000071

La Plata County, CO

Township: NENE 2 34N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
 Location Name: Hester 2, 4
 Location ID: 334302



Photo 1. View of the well disturbance taken from the entrance facing center. Note: Two wells share the disturbance.



API #: 067-08494, 09553

Inspection Photos
Location Name: Hester 2, 4
Location ID: 334302

10/26/23
+37.212391,-107.790465
73° E



Photo 2. View of the southern interim reclamation area facing east.

Inspection Photos
Location Name: Hester 2, 4
Location ID: 334302



10/26/23
+37.212742,-107.789698
343° N

Photo 3. View of the eastern cut slope interim reclamation area facing north.

Inspection Photos
Location Name: Hester 2, 4
Location ID: 334302



Photo 4. View of reference area comprised of smooth brome.