

# Final Reclamation Inspection

October 26th, 2023

Operator: Simcoe LLC - 10749

Location ID: 306845

Inspection Document #: 714000072

La Plata County, CO

Township: NESW 10 34N 9W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Webb Reeder A 2  
Location ID: 306845



**Photo 1.** View of the well disturbance taken from the entrance facing center.



API #: 067-08877

Inspection Photos  
Location Name: Webb Reeder A 2  
Location ID: 306845



**Photo 2.** View of the northern interim reclamation area facing southwest.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-08877

Inspection Photos  
Location Name: Webb Reeder A 2  
Location ID: 306845



**Photo 3.** View of the western interim reclamation area facing north.



Inspection Photos  
Location Name: Webb Reeder A 2  
Location ID: 306845



**Photo 4.** View of unused gates/equipment on location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-08877

Inspection Photos  
Location Name: Webb Reeder A 2  
Location ID: 306845



**Photo 5.** View of reference area comprised of sagebrush and western wheatgrass.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-08877