Form 9-331a
(Feb. 1951)

RECEIVED
BR OF OIL & GAS (SUBMIT IN TRIPLICATE)

JUN 8 - 1964 UNITED STATES
DEPARTMENT OF THE INTERIOR
U. S. GEOLOGICAL SURVEY GEOLOGICAL SURVEY
DENVER, COLORADO

RECEIVED
OCT 14 1968

COLO. OIL & GAS CONS. COMM.

Land Office **Denver**

Lease No. D-053004(A)

Unit C-034894

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	X	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

LINDEMAN......

STORRS........

GORE...........

MUNDINE.......

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 4 , 19 64

Well No. **1** is located **100** ft. from (N)/S line and **1217** ft. from (E)/W line of sec. **10 lot 2**

(NE¼ NE¼) 10 - T 1 N - 102W 6th P.M.
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Rangely **Rio Blanco** **Colorado**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **595** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

To set one joint surface casing and drill mancos shale test, or to

production. Estimated depth 3000 ft.

Drilled with cable tools.

Approved 6/17/64

E K Haymaker
Asst. District Engineer

DVR	
FJP	
HHM	✓
JAM	
UD	✓

02358066

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Teal Drilling Company**
Box 6

Address **Rangely, Colorado**

By *S. J. Rabourn*

Title **Operator**