

Operator: 8 NORTH LLC

Location Name: Silverback 36-A Pad

Loc ID: 443555

Inspection: 696305320



Exhibit A



Exhibit B

CA: Unused Chemical Tank and Stand West of Maint. Tank; see photos. Comply with Rule 606.

CA Resolution: Operator has removed the identified unused chemical tank and stand west of the maintenance tank to comply with Rule 606.

CA: Day Tanks - 2 Chemical Day Tanks on Northeast Side of Location - Missing Wildlife Netting; see photos. Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.

CA Resolution: Operator has removed the identified chemical day tanks on NE side of Location; Wildlife netting is no longer required.