


**Inspection Photos**  
**Operator: CAERUS PICEANCE LLC – 10456**  
**Location Name: PICEANCE CREEK UNIT #63-17**  
**Location ID: 314329 API #: 05-103-05173**  
**Inspection Date: 10/30/2023 Inspection Doc#: 693806514**



**Injection well during MIT**



**Form 21 field copy**