

Final Reclamation and Stormwater Inspection

Date: 10/26/2023

Operator: WHITING OIL & GAS CORPORATION - 96155

Location ID: 435875

Inspection Document #: 708200651

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Horsetail 29E Pad
Location ID: 435875



Photo 1. This location does not comply with Rule 1004. Operator submitted Form 4 Sundry Notices stating the above wells were not drilled. Location was not constructed at the proposed well location based off field observations. However, during this inspection, Staff observed that t-posts and wooden stakes remain on location, which is now considered debris, and will need to be removed in order to meet Rule 1004 standards.

Inspection Photos
Location Name: Horsetail 29E Pad
Location ID: 435875



Photo 2. See comments in Photo 1.