

Inspection Photos
Location Name: Cottonwood 08E-0504
Location ID: 439412



Energy and Carbon Management Commission
40.76773, -103.78151, 4672.9ft
10/24/2023 11:23:00



Energy and Carbon Management Commission
40.76756, -103.7806, 4681.6ft
10/24/2023 11:23:40

Photo 1 – Signs at Entrance

Photo 2 – Tank Battery



Inspection Photos
Location Name: Cottonwood 08E-0504
Location ID: 439412




Photo 3 – NFPA and Capacity Labels missing



Photo 4 – Tank Battery Sign



Inspection Photos
Location Name: Cottonwood 08E-0504
Location ID: 439412



Photo 5 – Stained Soil at Recycle Pump



Photo 6 – Unmarked Riser

Inspection Photos
Location Name: Cottonwood 08E-0504
Location ID: 439412



Photo 7 – Tank Battery



Photo 8 – Heater Treater

Inspection Photos
Location Name: Cottonwood 08E-0504
Location ID: 439412



Photo 9 – ECD and Flare



Photo 10 – Pumping Unit

Inspection Photos
Location Name: Cottonwood 08E-0504
Location ID: 439412



Photo 11 – Wellhead

