

Inspection Photos
Location Name: Thomason 37N-E4HZ
Location ID: 419956



Photo 1: Wellhead Location



Photo 2: Wellhead Sign

Inspection Photos
Location Name: Thomason 37N-E4HZ
Location ID: 419956



Photo 3: Wellhead



Photo 4: Debris

Inspection Photos
Location Name: Thomason 37N-E4HZ
Location ID: 419956



Photo 5: Wellhead Sign



Photo 6: Wellhead

Inspection Photos
Location Name: Thomason 37N-E4HZ
Location ID: 419956



Photo 7: Weeds



Photo 8: Wellhead Sign

Inspection Photos
Location Name: Thomason 37N-E4HZ
Location ID: 419956



Photo 9: Wellhead



Photo 10: Tank Battery Location

Inspection Photos
Location Name: Thomason 37N-E4HZ
Location ID: 419956



Photo 11: Centralized Tank Battery



Photo 12: Debris

Inspection Photos
Location Name: Thomason 37N-E4HZ
Location ID: 419956



Photo 13: Debris



Photo 14: Debris

Inspection Photos
Location Name: Thomason 37N-E4HZ
Location ID: 419956



Photo 15: Debris



Photo 16: Debris

Inspection Photos
Location Name: Thomason 37N-E4HZ
Location ID: 419956



Photo 17: Debris



Photo 18: Weeds

Inspection Photos
Location Name: Thomason 37N-E4HZ
Location ID: 419956



Photo 19: Debris/weeds



Photo 20: Debris

Inspection Photos
Location Name: Thomason 37N-E4HZ
Location ID: 419956




Photo 21: Debris




Photo 22: Debris

Inspection Photos
Location Name: Thomason 37N-E4HZ
Location ID: 419956



Energy & Carbon Management Commission
40.14719, -104.65989, 1463.8m, 314°
Oct 31, 2023 11:41:16

Photo 23: Debris