

**Inspection Photos**  
**Location Name: Haymaker 14N-4HZ**  
**Location ID: 428979**



**Photo 1: Location**



**Photo 2: Wellhead Location**



Inspection Photos  
Location Name: Haymaker 14N-4HZ  
Location ID: 428979



Photo 3: Wellhead Sign




Photo 4: Wellhead



Inspection Photos  
Location Name: Haymaker 14N-4HZ  
Location ID: 428979



Photo 5: Wellhead Sign



Photo 6: Wellhead



Inspection Photos  
Location Name: Haymaker 14N-4HZ  
Location ID: 428979



Photo 7: Centralized Tank Battery



Photo 8: Debris



**Inspection Photos**  
**Location Name: Haymaker 14N-4HZ**  
**Location ID: 428979**



**Photo 9: Debris**



**Photo 10: Debris**



**Inspection Photos**  
**Location Name: Haymaker 14N-4HZ**  
**Location ID: 428979**



**Photo 11: Debris**



**Photo 12: Debris**



Inspection Photos  
Location Name: Haymaker 14N-4HZ  
Location ID: 428979



Photo 13: Debris




Photo 14: Debris