

# Inspection Photos

10/18/2023

**Operator:** POC-I LLC - 10386

**Location ID:** 312756

**Inspection Doc:** 696205344

Moffat County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: POC-I LLC - 10386  
Location ID: 312756



**Photo 1:** Photos taken from the south end of the Location, facing north and northeast. Photos provide an overview of the Location. Areas left of the yellow line in the left photo require reclamation. Access road travels past the location and remains in use by the surface owner.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos  
Operator Name: POC-I LLC - 10386  
Location ID: 312756



**Photo 2:** Photos taken from the north end of the Location, facing south and northwest. Photos provide an overview of the Location. Areas right of the yellow line in the right photo require reclamation. Access road travels past the location and remains in use by the surface owner.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos  
Operator Name: POC-I LLC - 10386  
Location ID: 312756



**Photo 3:** Photo taken from the west end of the Location. Photo shows pipe that remains apparent at the pad surface. Operator appears to have cut the pipe at the surface, and backfilled with soil.



Inspection Photos  
Operator Name: POC-I LLC - 10386  
Location ID: 312756



October 18, 2023

**Photo 4:** Photo taken from the north end of the Location, facing south. Photo shows pipe equipment remaining on the Location. Arrow also shows Utility Pole remaining. Equipment require removal.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos  
Operator Name: POC-I LLC - 10386  
Location ID: 312756



**Photo 5:** Continued from photo 4. Photo shows pipe on the north end of the Location has not been properly covered, resulting in bird mortality.



Inspection Photos  
Operator Name: POC-I LLC - 10386  
Location ID: 312756



October 18, 2023

**Photo 6:** Photo shows anchor remaining on the southeast end of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources





**Photo 7:** Photo taken with use of a sUAS. Photo shows access road travels through the Location and is in use by the Surface Owner; areas beyond the road require reclamation (red polygon). Photo also shows utility equipment requiring removal.