

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SWSW

Location ID: 324072

Date: 10/30/2023



Location Entrance – Photo #07239



Wellhead – Photo #07240

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SWSW

Location ID: 324072

Date: 10/30/2023



Separator – Photo #07245



Tank Battery – Photo #07244

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SWSW

Location ID: 324072

Date: 10/30/2023



Debris – Photo #07246



Unprotected Soil Stockpile – Photo #07242

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SWSW

Location ID: 324072

Date: 10/30/2023



Unprotected Soil Stockpile – Photo #07243