

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/34-5

Location ID: 334816

Date: 10/31/2023



Location Entrance – Photo #07267



NW Corner of Location – Photo #07268

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/34-5

Location ID: 334816

Date: 10/31/2023



Wellheads – Photo #07277



Separators – Photo #07276

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/34-5

Location ID: 334816

Date: 10/31/2023



Tank Battery – Photo #07269




Tank Capacity not Posted – Photo #07271

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/34-5

Location ID: 334816

Date: 10/31/2023



Tank Capacity not Posted – Photo #07272

Debris in Tank Battery – Photo #07270

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/34-5

Location ID: 334816

Date: 10/31/2023



Unprotected Soil Stockpile – Photo #07274



Unprotected Soil Stockpile – Photo #07275