

Final Reclamation Inspection

October 12th, 2023

Operator: Hilcorp Energy Company - 10133

Location ID: 326462

Inspection Document #: 714000048

La Plata County, CO

Township: NENW 6 34N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Kendrick 3-6
Location ID: 326462

10/12/23
+37.249268,-107.788676
83° E



Photo 1. View of the well disturbance taken from the entrance facing center.



API #: 067-08147

Inspection Photos
Location Name: Kendrick 3-6
Location ID: 326462



Photo 2. View of the southern interim facing east.



Inspection Photos
Location Name: Kendrick 3-6
Location ID: 326462



10/12/23
+37.249412,-107.788058
259° W

Photo 3. View of the northern interim facing west.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08147

Inspection Photos
Location Name: Kendrick 3-6
Location ID: 326462



Photo 4. Debris within the western and northern interim areas.

Inspection Photos
Location Name: Kendrick 3-6
Location ID: 326462



Photo 5. Musk thistle observed flowering in various locations throughout the disturbance.



Inspection Photos
Location Name: Kendrick 3-6
Location ID: 326462



Photo 6. Reference area comprised of crested wheatgrass and intermediate wheatgrass.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08147