

Final Reclamation Inspection

October 12th, 2023

Operator: Enduring Resources LLC - 10633

Location ID: 326161

Inspection Document #: 714000055

La Plata County, CO

Township: NWSE 31 35N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Huber Dobbins 1-31
Location ID: 326161



Photo 1. View of the well pad disturbance taken from the entrance facing center.



API #: 067-07580

Inspection Photos
Location Name: Huber Dobbins 1-31
Location ID: 326161



Photo 2. view of the southern interim reclamation area facing east.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07580

Inspection Photos
Location Name: Huber Dobbins 1-31
Location ID: 326161



10/12/23
+37.255309,-107.786210
349° N

Photo 3. View of the eastern interim reclamation area facing north.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07580

Inspection Photos
Location Name: Huber Dobbins 1-31
Location ID: 326161



Photo 4. View of russian knapweed observed in the southeast corner of the disturbance/interim area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07580

Inspection Photos
Location Name: Huber Dobbins 1-31
Location ID: 326161



Photo 5. View of western interim reclamation area facing south. Vegetation establishment appears to be affected by active horse grazing. Disturbance is surrounded by a horse pasture dominated by smooth brome and western wheatgrass.

API #: 067-07580