


Inspection Photos  
Location: Celica 32-26  
Facility ID: 307777



Photo 1 –Well Site Placard

Photo 2 – Well Head, Unused Shed

**Inspection Photos**  
**Location: Celica 32-26**  
**Facility ID: 307777**



**Photo 3 – Onsite Pit**

**Photo 4 – Offsite Pit**

Inspection Photos  
Location: Celica 32-26  
Facility ID: 307777



Photo 5 – Pit Freeboard

Photo 6 – Pit Monitor

**Inspection Photos**  
**Location: Celica 32-26**  
**Facility ID: 307777**



**Photo 7 – Pit Monitor Readout, No Readout on screen**

**Photo 8 – Missing Rig Anchor Marker**

**Inspection Photos**  
**Location: Celica 32-26**  
**Facility ID: 307777**



**Photo 9 – Rig Ancho Marker**