

Inspection Photos
Location: Silverland 31-22 and Silverland 31-22TR
Facility ID: 334200



Photo 1 –Well Site Placard

Photo 2 – Silverland 31-22

Inspection Photos
Location: Silverland 31-22 and Silverland 31-22TR
Facility ID: 334200



Photo 3 – Pit Facility 361321, Fence is compromised on the SW corner

Photo 4 – Silverland 31-22 TR

Inspection Photos
Location: Silverland 31-22 and Silverland 31-22TR
Facility ID: 334200



Photo 5 – Pit Facility ID 301239, Pit liner compromised

Photo 6 – – Pit Facility ID 301239, Pit liner compromised