

Inspection Photos  
Location: Viking 34-15  
Facility ID: 308184



Photo 1 –Well Site Placard

Photo 2 – Well

**Inspection Photos**  
**Location: Viking 34-15**  
**Facility ID: 308184**



**Photo 3 – Pit Facility 265467**



**Photo 4 – Sediment Leaving North East Corner of location**



**Inspection Photos**  
**Location: Viking 34-15**  
**Facility ID: 308184**



**Photo 5 – Rutting and Riling on Access Road**



**Photo 6 – Rutting and Riling on Access Road**