

Inspection Photos

Loc: 321141

Operator: **LORENTZ OIL & GAS LLC**

Inspection Date: 10/31/2023

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west toward the location. The location is fenced and desirable vegetation has not reestablished.



Inspection Photos



Photo 2. Facing west at the location. This area with insufficient vegetation is approximately 120'x60'. There are likely impacted soils preventing vegetation growth.



Inspection Photos



Photo 3. Facing east at the location. This area with insufficient vegetation is approximately 120'x60'. There are likely impacted soils preventing vegetation growth.



Inspection Photos



Photo 5. Facing south toward the surrounding reference area which consists of native Blue grama, Sand drpseed, Buffalo grass ect.

