

Inspection Photos
Suckla Farms E #2 Flowline
Spill ID 479834/Remediation Project No 19028



Photo 1 – Site photo.



Photo 2 – Open excavation.

Inspection Photos
Suckla Farms E #2 Flowline
Spill ID 479834/Remediation Project No 19028



Photo 3 – Open excavation.



Photo 4 – Deteriorating BMPs.