

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Riley/1

Location ID: 335013

Date: 11/2/2023



Location Entrance – Photo #07300



East End of Location – Photo #07301

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Riley/1

Location ID: 335013

Date: 11/2/2023



Wellheads – Photo #07302



Separators – Photo #07305

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Riley/1

Location ID: 335013

Date: 11/2/2023



Tank Battery – Photo #07303



Wildlife Entry Hazard – Photo #07307

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Riley/1

Location ID: 335013

Date: 11/2/2023



Wildlife Entry Hazard – Photo #07308



Wildlife Entry Hazard – Photo #07309