

Inspection Photos  
Location Name: M Brophy 1-06  
API Number: 125-07382



1. Well sign at well location.



2. View of wellhead.

Inspection Photos  
Location Name: M Brophy 1-06  
API Number: 125-07382



3. Pump Jack with Horsehead removed.



4. Additional view of Pump Jack.



Inspection Photos  
Location Name: M Brophy 1-06  
API Number: 125-07382



5. Produced water tank sign.



6. Well location overview.

Inspection Photos  
Location Name: M Brophy 1-06  
API Number: 125-07382



7. Well sign at remote gas meter run.



8. View of remote gas meter shed.