

**Inspection Photos**  
**Location Name:** Foose USX/A18-23  
**Location #:** 420665



**Photo #1**

**Foose A18-23 (123-32666) Wellsite**  
**Plugged & Abandoned | PA**  
**Plugging Ops; Cementing: Initial plugs-2**



**Photo #2**

**Foose A18-23 Wellsite**  
**Plugged & Abandoned | PA**  
**Plugging Ops; Cementing: Initial plugs-2**  
*Site safety signage*






**Inspection Photos**  
**Location Name: Foose USX/A18-23**  
**Location #: 420665**



**Photo #3**

**Foose A18-23 Wellsite**  
**Plugged & Abandoned | PA**  
**Plugging Ops; Cementing: Initial plugs-2**  
*Wellsite entrance*



**Photo #4**

**Foose A18-23 Wellsite**  
**Plugged & Abandoned | PA**  
**Plugging Ops; Cementing: Initial plugs-2**  
**JSA: 2023-11-03**



## Inspection Photos

Location Name: Foose USX/A18-23

Location #: 420665



Photo 5

Foose A18-23 Battery site

**Plugged & Abandoned | PA**

**Plugging Ops; Cementing: Initial plugs-2**

Battery sign

*prior photo*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources