

Inspection Photos
Location Name: HOLMAN-65N64W/14SWNE
Location ID: 323370



Photo #1

Holman 14-1 Battery site

Inactive | Shut-down

Tank(s): SE corner



Photo #2

Holman 14-1 Battery site

Inactive | Shut-down

Separator(s)

prior photo



Inspection Photos

Location Name: HOLMAN-65N64W/14SWNE

Location ID: 323370



Photo #3

Holman 14-1 Battery site

Inactive | Shut-down

Separator(s) produced H2O vault

CA: Overgrown Vegetation

prior photo



Photo #4

Holman 14-1 Battery site

Inactive | Shut-down

Separator(s) produced H2O vault

Overgrown Vegetation: Mitigated



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HOLMAN-65N64W/14SWNE
Location ID: 323370



Photo #5
Holman 14-1 Battery site
Inactive | Shut-down
Battery sign
prior photo



Photo #6
Holman 14-1 (123-12922) Wellsite
Temporarily Abandoned | TA
prior photo

