

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/33SESW

Location ID: 334862

Date: 11/2/2023



Location Entrance – Photo #07343



Wellheads – Photo #07344

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/33SESW

Location ID: 334862

Date: 11/2/2023



Separators – Photo #07345



Tank Battery – Photo #07346