

Interim & Stormwater Inspection

September 13, 2023

Operator: Crestone Peak, # 10633

Location ID: 332743

Inspection Document # 709400560

Weld, CO

SWSE, 10 3N 65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Aristocrat Angus 6-4-10 Well
& Tank Battery
Location ID: 332743



Photo 1. Photo of location sign on site.



Photo 2. Photo of tank battery. Facing northwest.

Inspection Photos
Location Name: Aristocrat Angus 6-4-10 Well
& Tank Battery
Location ID: 332743

Sep 13, 2023 at 1:27:40 PM
La Salle CO 80645
United States



Photo 3. Photo of cattle guard and fencing at entrance of tank battery. Photo taken facing south east.

Sep 13, 2023 at 1:26:15 PM
La Salle CO 80645
United States



Photo 4. Photo of equipment on tank battery. Photo taken facing east.

Inspection Photos
Location Name: Aristocrat Angus 6-4-10 Well
& Tank Battery
Location ID: 332743

Sep 13, 2023 at 1:33:34 PM
La Salle CO 80645
United States



Photo 5. Photo of weeds (kosha) at well head facing south

Sep 13, 2023 at 1:33:43 PM



Photo 6. Photo of weeds (kosha) at perimeter of wellhead working pad area and reclaimed area. Photo taken facing northeast.

Inspection Photos
Location Name: Aristocrat Angus 6-4-10 Well
& Tank Battery
Location ID: 332743

Sep 13, 2023 at 1:33:46 PM



Photo 7. Photo of weeds (kosha) at perimeter of wellhead working pad area and reclaimed area. Photo taken facing South.

Sep 13, 2023 at 1:34:08 PM
La Salle CO 80645
United States



Photo 8. Photo of reclaimed area around wellhead. Photo taken facing Northeast.