

Interim & Stormwater Inspection

September 13, 2023

Operator: Crestone Peak, # 10633

Location ID: 305580

Inspection Document # 709400562

Weld, CO

NWSE, 3 3N 65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Aristocrat Angus 2-4-3X Well
Location ID: 305580



Photo 1. Photo of location sign on site.



Photo 2. Photo of Wellhead. Facing east.

Inspection Photos
Location Name: Aristocrat Angus 2-4-3X Well
Location ID: 305580



Photo 3. Photo of wellhead and piping in cellar. Photo taken facing south southeast.



Photo 4. Photo of bare area and weeds (kosha and russian thistle) in reclaimed area. Photo taken facing east.

Inspection Photos
Location Name: Aristocrat Angus 2-4-3X Well
Location ID: 305580

Sep 13, 2023 at 1:39:50 PM
La Salle CO 80645
United States



Photo 5. Photo of weeds (kosha & russian thistle) at perimeter of wellhead working pad area and reclaimed area. Photo taken facing north.

Sep 13, 2023 at 1:39:58 PM
La Salle CO 80645
United States



Photo 6. Photo of weeds (kosha & russian thistle) at perimeter of wellhead working pad area and reclaimed area. Photo taken facing west.

Inspection Photos
Location Name: Aristocrat Angus 2-4-3X Well
Location ID: 305580

Sep 13, 2023 at 1:40:08 PM
La Salle CO 80645
United States



Photo 7. Photo of weeds (kosha & russian thistle) at perimeter of wellhead working pad area and reclaimed area. Photo taken facing west.

Sep 13, 2023 at 1:42:22 PM
La Salle CO 80645
United States



Photo 8. Photo of undisturbed area for reference vegetation. Photo taken facing Northeast.