

Final Reclamation and Stormwater Inspection

October 20, 2023

Operator: Western Operating Co- #95620

Location ID: 319767

Inspection Document #: 709400590

Adams County, CO

SWSW Section 24 T5N R59W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Downing Ralph 24-2
Location ID: 319767

Oct 20, 2023 at 12:51:30 PM
Deer Trail CO 80105
United States



Photo 1. Photo taken facing northwest of perimeter fence of reclamation area and a comparison of vegetation between reclaimed and non impacted area.

Oct 20, 2023 at 12:51:34 PM
Deer Trail CO 80105
United States



Photo 2. Photo taken facing west of perimeter fence of reclamation area and a comparison of vegetation between reclaimed and non impacted area.

Inspection Photos
Location Name: Downing Ralph 24-2
Location ID: 319767

Oct 20, 2023 at 12:51:55 PM
Deer Trail CO 80105
United States



Photo 3. Photo taken facing northwest of perennial grasses and weeds (koshia & russian thistle) on site.

Oct 20, 2023 at 12:51:58 PM
Deer Trail CO 80105
United States



Photo 4. Photo taken facing west of perennial grasses and weeds (koshia & russian thistle) and a bare area of exposed soil on site.



Inspection Photos
Location Name: Downing Ralph 24-2
Location ID: 319767

Oct 20, 2023 at 12:52:31 PM
Deer Trail CO 80105
United States



Photo 5. Photo taken facing east of weeds (kochia & russian thistle) on site.

Oct 20, 2023 at 12:52:55 PM
Deer Trail CO 80105
United States



Photo 6. Close up photo illustrating some of the desirable perennial grasses. Photo taken facing east.

Inspection Photos
Location Name: Downing Ralph 24-2
Location ID: 319767

Oct 20, 2023 at 12:53:52 PM
Deer Trail CO 80105
United States



Photo 7. Photo taken facing east of weeds (koshia & russian thistle) and a bare area of exposed soil.

Oct 20, 2023 at 12:54:38 PM
Deer Trail CO 80105
United States



Photo 8. Photo taken facing south of perennial grasses and weeds (koshia & russian thistle) and a bare area of exposed soil.



Oct 20, 2023 at 12:55:08 PM
Deer Trail CO 80105
United States



Photo 9. Photo taken facing west of established perennial grasses. Density of desirable species is lacking for final reclamation standards.

Inspection Photos
Location Name: Downing Ralph 24-2
Location ID: 319767

Oct 20, 2023 at 2:14:15 PM



Photo 10. Photo taken facing east of non impacted area for vegetation reference and comparison.

