

# Interim Reclamation and Stormwater Inspection

October 23, 2023

Operator: Western Operating Co- #95620

Location ID: 319759

Inspection Document #: 709400607

Adams County, CO

NWSW Section 24 T3S R59W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Downing Ralph 24-1  
Location ID: 319759

Oct 23, 2023 at 1:25:50 PM  
Deer Trail CO 80105  
United States



Photo 1. Photo taken facing west of location sign.

Oct 23, 2023 at 1:26:01 PM  
Deer Trail CO 80105  
United States



Photo 2. Photo taken facing west of metal structure around injection wellhead.



Inspection Photos  
Location Name: Downing Ralph 24-1  
Location ID: 319759

Oct 23, 2023 at 1:26:17 PM  
Deer Trail CO 80105  
United States



**Photo 3.** Photo taken facing northeast of perennial grasses and weeds (koshia & russian thistle) on site.

Oct 23, 2023 at 1:26:21 PM  
Deer Trail CO 80105  
United States



**Photo 4.** Photo taken facing west of perennial grasses and weeds (koshia & russian thistle) and cut slope of original pad. site has not been recontoured.



Inspection Photos  
Location Name: Downing Ralph 24-1  
Location ID: 319759

Oct 23, 2023 at 1:26:27 PM  
Deer Trail CO 80105  
United States



**Photo 5.** Photo taken facing north of weeds (kochia & russian thistle) in the foreground.

Oct 23, 2023 at 1:27:05 PM  
Deer Trail CO 80105  
United States



**Photo 6.** Photo taken facing southwest of weeds (koshia & russian thistle) and perennial grasses.

Inspection Photos  
Location Name: Downing Ralph 24-1  
Location ID: 319759

Oct 23, 2023 at 1:27:45 PM  
Deer Trail CO 80105  
United States



**Photo 7.** Photo taken facing northeast of weeds (koshia & russian thistle) and a bare area of exposed soil.

Oct 23, 2023 at 1:28:00 PM  
Deer Trail CO 80105  
United States



**Photo 8.** Photo taken facing south of eroding bare area of exposed soil.

Oct 23, 2023 at 1:29:31 PM  
Deer Trail CO 80105  
United States



**Photo 9.** Photo taken facing east of non impacted area for vegetation reference and comparison.