

# Interim & Stormwater Inspection

October 23, 2023

Operator: KP Kauffman Co, # 46290

Location ID: 320317

Inspection Document # 709400611

Adams, CO

NWNW, 16 3S 59W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: DNR Hearman State 11-16

Location ID: 320317



**Photo 1.** Photo of location sign on site.



**Photo 2.** Photo of Tanks on site, facing east.

# Inspection Photos

Location Name: DNR Hearman State 11-16

Location ID: 320317

Oct 23, 2023 at 2:27:25 PM  
7148-7196 Hanks Crossing Rd  
Byers CO 80103  
United States



**Photo 3.** Photo of weeds (Kosha & russian thistle) on site, facing north.

Oct 23, 2023 at 2:27:39 PM  
7148-7196 Hanks Crossing Rd  
Byers CO 80103  
United States



**Photo 4.** Photo of weeds (kosha & russian thistle) on site facing northwest.

## Inspection Photos

Location Name: DNR Hearman State 11-16

Location ID: 320317

Oct 23, 2023 at 2:28:06 PM  
7148-7196 Hanks Crossing Rd  
Byers CO 80103  
United States



**Photo 5.** Photo of weeds (Goathead) on site, facing southeast

Oct 23, 2023 at 2:28:39 PM  
7148-7196 Hanks Crossing Rd  
Byers CO 80103  
United States



**Photo 6.** Photo of breached berm around equipment on site facing north.

# Inspection Photos

Location Name: DNR Hearman State 11-16

Location ID: 320317

Oct 23, 2023 at 2:30:44 PM  
7148-7196 Hanks Crossing Rd  
Byers CO 80103  
United States



**Photo 7.** Photo of weeds (Kosha & russian thistle) around produced water pit, facing southeast. Pit # 107681

Oct 23, 2023 at 2:31:42 PM  
7148-7196 Hanks Crossing Rd  
Byers CO 80103  
United States



**Photo 8.** Photo of weeds (Kosha & russian thistle) around produced water pit and reeling on pit walls facing southwest. Pit # 107681

## Inspection Photos

Location Name: DNR Hearman State 11-16

Location ID: 320317

Oct 23, 2023 at 2:32:35 PM  
7148-7196 Hanks Crossing Rd  
Byers CO 80103  
United States



**Photo 9.** Photo of produced water tank emptying into pit on site, facing south

Oct 23, 2023 at 2:37:37 PM  
Byers CO 80103  
United States



**Photo 10.** Photo of Wellhead on site facing northeast.

## Inspection Photos

Location Name: DNR Hearman State 11-16

Location ID: 320317

Oct 23, 2023 at 2:37:45 PM  
Byers CO 80103  
United States



**Photo 11.** Photo of weeds (Kosha & russian thistle) on wellhead site, facing east.

Oct 23, 2023 at 2:37:56 PM  
Byers CO 80103  
United States



**Photo 12.** Photo of weeds (kosha & russian thistle) on wellhead site facing south.

Inspection Photos

Location Name: DNR Hearman State 11-16

Location ID: 320317

Oct 23, 2023 at 2:41:26 PM  
7149-7197 Hanks Crossing Rd  
Byers CO 80103  
United States



**Photo 13.** Photo of in accessible, washed out access road to wellhead from county road, facing east

Oct 23, 2023 at 2:41:46 PM  
7149-7197 Hanks Crossing Rd  
Byers CO 80103  
United States



**Photo 14.** See photo 13 comments.