

Interim and Stormwater Inspection

October 25, 2023

Operator: Crestone Peak Resources Operating- #10633

Location ID: 455198

Inspection Document #: 709400618

Arapahoe County, CO

NWSW Section 26 T4S R65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Chico 4-65 26-25
Location ID: 455198

Oct 25, 2023 at 1:28:08 PM
Aurora CO 80137
United States



Photo 1. Photo taken of location sign at wellhead, facing east.

Oct 25, 2023 at 1:30:56 PM
Aurora CO 80137
United States



Photo 2. Photo taken of wells on site. Photo taken facing east.

Inspection Photos
Location Name: Chico 4-65 26-25
Location ID: 455198

Oct 25, 2023 at 1:30:10 PM
Aurora CO 80137
United States



Photo 3. Photo taken of tank battery on pad. Photo taken facing southwest.

Oct 25, 2023 at 1:32:46 PM
Aurora CO 80137
United States



Photo 4. Photo taken of drainage ditch around pad, with large rock check dams and rock rundowns to culvert. Photo taken facing west.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400618

Inspection Photos
Location Name: Chico 4-65 26-25
Location ID: 455198

Oct 25, 2023 at 1:32:59 PM
Aurora CO, 80137
United States



Photo 5. Photo taken of mowed reclaimed area. Photo taken facing east.

Oct 25, 2023 at 1:33:01 PM
Aurora CO 80137
United States



Photo 6. Photo taken of mowed reclaimed area. Photo taken facing northeast.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400618

Inspection Photos

Location Name: Chico 4-65 26-25

Location ID: 455198

Oct 25, 2023 at 1:34:31 PM
Aurora CO 80137
United States



Photo 7. Photo taken of mowed re-vegetated area. Photo taken facing south.

Oct 25, 2023 at 1:36:13 PM
Aurora CO 80137
United States



Photo 8. Photo taken of large sediment . Photo taken facing southeast.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400618

Inspection Photos
Location Name: Chico 4-65 26-25
Location ID: 455198

Oct 25, 2023 at 1:36:33 PM
Aurora CO 80137
United States



Photo 9. Photo taken of sediment basin and rock check dams in drainage leading to it. Photo taken facing southeast.

Oct 25, 2023 at 1:38:50 PM
Aurora CO 80137
United States



Photo 10. Photo of mowed reclaimed area and wattles for sediment control. Photo taken facing east.

Inspection Photos

Location Name: Chico 4-65 26-25

Location ID: 455198

Oct 25, 2023 at 1:41:44 PM
Aurora CO 80137
United States



Photo 10. Photo taken of Longspine sandbur an undesirable plant species found throughout the reclaimed area.

Oct 25, 2023 at 1:42:19 PM
Aurora CO 80137
United States



Photo 11. Photo of Longspine sandbur burs in pant cuff, demonstrating mowing is not sufficient to prevent spread of seeds.