

# Interim and Stormwater Inspection

October 25, 2023

Operator: Crestone Peak Resources Operating- #10633

Location ID: 471001

Inspection Document #: 709400625

Arapahoe County, CO

SWNW Section 28 T4S R65W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources


## Inspection Photos

Location Name: Rush North 4-65 29-30

Location ID: 471001



**Photo 1.** Photo taken of location sign at wellhead, facing east.



**Photo 2.** Photo taken of wells on site. Photo taken facing northeast.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 709400625



Inspection Photos  
Location Name: Rush North 4-65 29-30  
Location ID: 471001

Oct 25, 2023 at 2:25:42 PM  
Aurora CO 80018  
United States



**Photo 3.** Photo taken of tank battery on pad. Photo taken facing northwest.

Oct 25, 2023 at 2:28:37 PM  
Aurora CO 80018  
United States



**Photo 4.** Photo taken of drainage and rock check dams, along access road. Photo taken facing Northwest.



**Inspection Photos**  
**Location Name: Rush North 4-65 29-30**  
**Location ID: 471001**

Oct 25, 2023 at 2:28:39 PM  
Aurora CO 80018  
United States



**Photo 5.** Photo taken of interim reclamation area and drainage with large rock check dams . Photo taken facing east.

Oct 25, 2023 at 2:29:02 PM  
Aurora CO 80018  
United States



**Photo 6.** Photo taken of interim reclamation area. Photo taken facing northwest.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 709400625



## Inspection Photos

Location Name: Rush North 4-65 29-30

Location ID: 471001

Oct 25, 2023 at 2:31:04 PM  
Aurora CO 80018  
United States



**Photo 7.** Photo taken of mowed re-vegetated cut slope. Photo taken facing northeast.

Oct 25, 2023 at 2:31:05 PM  
Aurora CO 80018  
United States



**Photo 8.** Photo taken of mowed re-vegetated cut slope. Lower portion of cut slope does not appear to be moving toward revegetation standards. reseed with stabilization needed. Photo taken facing northeast. Area outlined in red.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 709400625



## Inspection Photos

Location Name: Rush North 4-65 29-30

Location ID: 471001

Oct 25, 2023 at 2:31:34 PM  
Aurora CO 80018  
United States



**Photo 9.** Photo taken of mowed interim reclamation area. Photo taken facing northwest.

Oct 25, 2023 at 2:34:10 PM  
Aurora CO 80018  
United States



**Photo 10.** Photo taken of mowed interim reclamation area and topsoil stockpile outlined with wattles. . Photo taken facing west.



## Inspection Photos

Location Name: Rush North 4-65 29-30

Location ID: 471001

Oct 25, 2023 at 2:35:05 PM  
Aurora CO 80018  
United States



**Photo 10.** Photo taken of rock check dams leading to large sediment basin. Photo taken facing west.

Oct 25, 2023 at 2:35:38 PM  
Aurora CO 80018  
United States



**Photo 11.** Photo taken of large sediment basin and rock rundowns. Photo taken facing north.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 709400625